





## Surface Go Scanner Installation

# Scanner only assembly for Surface Go



- 1 - Shown are the parts included in the Scanner Only Kit SG-SCN-ONLY-KIT-DFS.
- 2 - Install Tablet into the Case per instructions included with Case. Make sure the Scanner USB PCB does not extend into Case.




Remove and keep M3 x 8 mm long Flat Head screw.


Remove and keep (2) M3 x 10 mm long Flat Head screws.

- 3 - Remove M3 x 8 & (2) M3 x 10 Flat Head screws.

# Scanner only assembly for Surface Go



4 - Install the Scanner Filler Plate.




5 - Re-install the M3 x 8 and (2) M3 x 10 Flat Head screws.




6 - Install the Scanner Connector Cover using (2) M2 x 3 Pan Head screws.

# Scanner only assembly for Surface Go




USB Type C connector

7 - Locate USB Type C connector in tablet.



8 - Plug USB Type C PCB into USB Type C connector as shown.

# Scanner only assembly for Surface Go



9 - Install Vanity Cover over USB Type C PCB. Ensure wires are aligned in Vanity Cover clearance area so that wires are not pinched.



10 - Install the M3 x 5 Pan Head screw.



11 - Vanity Cover should look like this when properly installed.