


10




Surface Pro Scanner Installation

Scanner only assembly for Surface Pro

xCase for Surface Installation Instructions









- 1 Insert tablet into the case per the instructions on insert.
- 2 Insert type a pcb into usb port
- 3 Install USB Cover using 2 M2x3mm PH screws
- 4 Install 1 M3x5mm wafer head screw

